SITE NAME : RAY WICHERT PROPERTY

SITE LOCATION: CLINTON, OK

SITE NUMBER : OKD987095049

FILE LOG # : 180

## ROUTE SLIP

## HAZARDOUS WASTE SITE - INSPECTION REPORT

	INITIALS   DATE   TIME (HOURS)
1. MARK MCCASLAND	MEM  5/24/93  0
2. WARREN NORRIS	1386 from 1925/831
<ol> <li>JO TAYLOR         (Cover memo, Xerox copies of report,         log out of file, file)         (Copies to Hickam, Wright 6H-ES)</li> </ol>	

FILE CODE: SFD-24-1-4

BOOK REGISTER LOG #: 1867



## INSPECTION REPORT REVIEW POTENTIAL HAZARDOUS WASTE SITE

POTENTIAL MASARDOOS WASTE SITE	
SITE NAME : RAY WICHERT PROPERTY LOCATION : CLINTON, OK SITE NUMBER: OKD987095049 SURVEY DATE:/ / INSPECTED BY: STATE FIT TAT OTHER: LABORATORY :CLPEPAOTHER	
RECEIVED FROM: DATE RECEIVED://_	
SAMPLE TYPE(s):	
SOIL SURFACE WATER GROUND WATEP. DRINKING WATER off / on -site off / on -site off / on -site	
CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological	
FOLLOW UP (Y/N):  (Re) Sampling Requested Further Action is URGENT  Locate Drinking Water Sources Keep Site Active ("N"=No Further Action) Concur with Report Recommendations	
SUMMARY:	
Lack of tayete & viable mein of transport of the hazanlown materials on-site. DW sources not threatened. We concern	
materials on-site. DW sources not fareatized. We concern	
with "six Evaluation accomplished" and no-further-	
action recommendation.	

Mand - M. Callan ENGINEER/REVIEWER ford & Podriges for FWN 5 125193